ECS Configuration Change Request Page 1 of Pages						
CCR No. 98- 00	8/ Logged	Date 1/22/98	Rev.	Request T	ype CCR	
Priority Routine	X Urgent	Emergency [Affected Release	Rel. 2	Change Class	II
Title GSFC and SMC Revised At-Launch Hardware Design						
Documents Affecte Version 2.0 Hardware	Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or Tech Reference None					
TDS-001 Rev.01						
RTM Change Start New Baseline						
Problem						
No Problem, See Solut	ion					
Proposed Solution		<u></u>				
•						1
The attached document incorporates changes to the Goddard and SMC DAAC Hardware Diagram as a of result hardware upgrades at Goddard in the Dec. 1997 timeframe.						
	3					
Need Da	te: 1/23/98					
Impact Analysis:	7-1-1/	<u>.</u>				
Organizations Affected	: ВОО □	Contracts	ECS Chief Eng	FOS 🗍	M&O [$\overline{\mathbf{x}}$
Procurement] 00 🗆	Rel. Dev	Rel. A	Rel. C	SCDO Arch.	_ ,
Science Off	Security	Subcontrot	Sys. Eng X	Sys Verf		
Cost:	None X	Small	Medium	Large		
Cabadula		(Not exceeding \$100,000)	(\$100,000 to \$500,000)	(Over \$500,000)		
Additional LOC	None X	Other	Man-Month			
			wan-workin			
Materials			41 41-		* - A	
Originator Mark Alab	astro, HW Engineer	Mark Alabastro	the let		22 Jan 189	<u> </u>
		Signature	$\sim \infty \setminus \sim \sim$	ΛN	Date	
Office SED-HW Eng.	Office Manager	Randall Miller	wall for My	<u>Var</u>	1/22/48	
		Signature			Date	
Disposition	Approved 💢	Approved w/Comm	nent Forw	ard	Disapproved [_
Comments:			\sim			
			\bigcap \bigcap			
	COR Obelies	TIN/	0//	1/2	2/98	ľ
	CCB Chairperson	Signature	in			te

CM010C96